

OSHIMURA

RESEARCH&DEVELOPMENT OF AMERICA, INC


5420 DANIELS STREET STE A, CHINO CA. 91786 · (800)634-9166 · (909)628-4722 · FACSIMILE (909)591-2198


www.yoshimura-rd.com

PERFORMANCE EXHAUST SYSTEM

HONDA 02-03 CBR954RR 00-01 CBR929RR

CB93050C	ZYCLONE BOLT-ON SYSTEM
CB93250	RACE ONLY BOLT-ON SYSTEM





Note: Dyno graphs are for comparison use only. Actual results may vary depending on operating and motorcycle condition.





Caution: Exhaust system can be extremely hot. Let motorcycle cool down before beginning installation.

Note: Read through all instructions before beginning installation.

Tools Needed:

12mm socket 3/8" ratchet and extension 12mm wrench Torque wrench

Installation Steps:

- 1 Remove stock muffler and gasket.
- 2 Install new muffler gasket. (Not supplied-Honda part no. 18291-MV400)
- 3 Install Yoshimura muffler using supplied bolts. Torque bolts to 2.3 kg-m (16.5 lb-ft)
- 4 Apply heat insulator to inside of muffler clamp and slide clamp onto muffler. (note direction of clamp in Fig. 2)
- 5 Mount clamp to stock muffler bracket using stock bolt, washer, and nut. (see Fig. 2) Torque bolt to 2.5 kg-m (18 lb-ft)
- 6 Before starting, check for proper clearance between new muffler and motorcycle. (i.e. swing-arm, passenger footpeg, rear wheel, etc.) If any problem is found, please carefully follow through the installation steps again. If problem still persists, please call Yoshimura tech. Dept. at (800)634-9166 / in CA (909)628-4722

Note: After starting motorcycle, it is normal for new muffler to smoke until oil residue burns off.




Fig. 1





Fig. 2

Part List: Page 3


#CB930SOC/CB932SO



Parts Diagram

NO.	DESCRIPTION	QTY	PART#
1	Muffler Assembly	1	**
2	Stainless Steel Muffler Clamp	1	C500S8ASX
3	8 x 20mm Hex Head Bolt	3	M8X20H
**	5" Heat Insulator	1	HT SHLD5
**	Yoshimura Vinyl Sticker	1	17029

Nuts and Bolts Guide (Actual Size):



8mm x 20mm Flange Hex Bolt